

US 101/BAY VIEW ROAD



US 101 & Bay View Road



Southbound US 101 Approach



Northbound US 101 Approach




Eastbound Bay View Road Approach



Westbound Bay View Road Approach


TRAFFIC OPERATIONS 30TH-HIGHEST HOUR CONDITIONS

2005




	MAJOR	MINOR
V/C	= 0.27	0.22
Delay	= 1	25
LOS	= A	C

2027



	MAJOR	MINOR
V/C	= 0.39	0.72
Delay	= 11	96
LOS	= B	F

LANE GEOMETRY



Lane Geometry Diagram