


US 101/IMMONEN ROAD




Southbound US 101 Approach



Northbound US 101 Approach


TRAFFIC OPERATIONS 30TH-HIGHEST HOUR CONDITIONS

2005




	MAJOR	MINOR
V/C	= 0.59	0.23
Delay	= 1	35
LOS	= A	D

2027



	MAJOR	MINOR
V/C	= 0.89	0.76
Delay	= 14	>150
LOS	= B	F

LANE GEOMETRY



Westbound Immonen Road Approach