

US 101/LANCER STREET-SEAGROVE DRIVE



Southbound US 101 Approach



Northbound US 101 Approach




Eastbound Lancer Street Approach



Westbound Lancer Street Approach


TRAFFIC OPERATIONS 30TH-HIGHEST HOUR CONDITIONS

2005



	MAJOR	MINOR
V/C	= 0.53	0.30
Delay	= 1	63
LOS	= A	F

2027



	MAJOR	MINOR
V/C	= 0.80	>2.0
Delay	= 13	>150
LOS	= B	F

LANE GEOMETRY

